



Port of Camas/Washougal

TO: Marina Tenants
FR: Port Office Management

We are happy to occasionally retie a boat in order to protect your property and our marina, however, our maintenance department is once again experiencing an epidemic of improperly or inadequately tied boats. As stated in Item L, on page 9 in the Marina Policy Manual: *“Boat owners are responsible for adequate fendering to protect marina facilities and adjacent vessels and for securely mooring their boats with adequate bow, stern and spring lines. Two or more lines are required. No lines shall cross walkways or be tied to the 4x4 structural members.”*

The chart below shows the proper mooring lines that are recommended for the size of your boat. We have found that in no case is “ski rope” adequate.

<u>Boat Weight</u>	<u>Use</u>	<u>Rope Size & Type</u>
2,385 lbs.		1 / 2” Nylon Rope
3,700 lbs.		3 / 8” Nylon Rope
3,960 lbs.		5 / 8” Nylon Rope
4,200 lbs.		1 / 2” Poly Rope
6,400 lbs.		1 / 2” Nylon Rope

Please secure your boat using one of the methods shown in the diagram below. We thank you for your help in this matter! If you have any questions, please call the Port maintenance department at 835-2196 ext. 106.

